

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	6	"5583337"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 17:28
L2	7	("3791741" "3968368" "4064534").PN. OR ("5583337").URPN.	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/02/10 17:32
S1	1	dalstra-j\$.in.	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/29 14:50
S2	2154	"65".class.	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/29 14:50
S3	71	S2 and "near" near20 infrared	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/29 14:50
S4	12	S3 and sensor	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/29 14:51
S5	15	S3 and filter	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/29 14:51
S6	4	S5 and sensor	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/29 14:51
S7	4	"6188079"	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/29 14:55
S8	5	"5583337"	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/29 14:57
S9	649	"near" near infrared near filter	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/29 15:01
S10	2	S9 and thermal imaging	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/29 15:02
S11	76	regional measurement	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/29 15:25
S12	4	S11 and quality control	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/01/29 15:25
S13	2161	"65".class.	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/02/05 14:51

S14	31	S13 and ((infra red or infrared or IR) near10 (sensor or sensing or detect\$4 or measur\$5 or expos\$4) near10 (temperat\$3 or heat\$4 or furnace))	US-PGPUB; USPAT; USOCR	ADJ	ON	2009/02/05 14:58
S15	14	(interior or internal or inside or inter\$3 or intra\$4) near "10" (wall or face or surface or plane) near10 (radiation or emission or wavelength or infrared)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 16:31
S16	553	(interior or internal or inside or inter\$3 or intra\$4) near "10" (wall or face or surface or plane) and (radiation or emission or wavelength or infrared)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 16:32
S17	398	S16 and (glass or plastic\$3 or plastique\$3 or steel)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 16:32
S18	796	(glass or plastic or steel) near10 (thermomeasure or thermography or thermographic or pyrometer)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 16:32
S19	144	S17 and (measure or gauge or quantity)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 16:33
S20	199	S18 and infrared	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 16:33

S21	33	S19 and (quality control or process control or product control)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 16:33
S22	156	S20 and glass	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 16:35
S23	36	65/29.12 and 65/29.18	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 16:52
S24	2161	"65".class.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 16:56
S25	46	S24 and pyrometer	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 16:56
S26	3	S24 and thermography	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 17:04
S27	1390	infrared measur\$5	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 17:04
S28	0	S27 and (hot near glass near process\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 17:08

S29	7	S27 and (glass near process\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2009/02/10 17:09
-----	---	------------------------------------	---	-----	----	---------------------

2/10/2009 5:40:24 PM

C:\Documents and Settings\kaziz\My Documents\EAST\Workspaces\10524454.wsp